

Overview

Models

HP X130 CX4 XENPAK Transceiver

JD502A

Product overview

JD502A HP X130 CX4 XENPAK Transceiver provides full duplex 10 Gigabit CX4 connections for up to 15m over copper CX4 cable.

Features and benefits

Warranty and support

- **1-year warranty:** with advance replacement and 30-calendar-day delivery (available in most countries)
- **Electronic and telephone support:** limited electronic and telephone support is available from HP; refer to: www.hp.com/networking/warranty for details on the support provided and the period during which support is available
- **Software releases:** refer to: www.hp.com/networking/warranty for details on the software releases provided and the period during which software releases are available for your product(s)



Technical Specifications

| | | | |
|---|----------------------------|--|--|
| HP X130 CX4 XENPAK Transceiver (JD502A) | Ports | 1 CX4 10-GbE port (IEEE 802.3ak Type 10GBASE-CX4); Duplex: full only | |
| | Connectivity | Connector type | CX4 |
| | Physical characteristics | Dimensions | 4.76(d) x 1.42(w) x 0.69(h) in. (12.1 x 3.6 x 1.74 cm) |
| | Environment | Operating temperature | 32°F to 158°F (0°C to 70°C) |
| | Electrical characteristics | Power consumption typical | 1.6 W |
| | Cabling | Maximum distance: | |
| | | <ul style="list-style-type: none">15m CX4 Cable | |
| | | Cable length | 15m |
| | Services | Refer to the HP website at: www.hp.com/networking/services for details on the service-level descriptions and product numbers. For details about services and response times in your area, please contact your local HP sales office. | |

To learn more, visit www.hp.com/networking

© Copyright 2011 Hewlett-Packard Development Company, L.P. The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

